

RCSL: 44 - RT 1911

MANDATORY <input type="checkbox"/>	RETROFIT ON FAILURE <input checked="" type="checkbox"/>
WARRANTY <input checked="" type="checkbox"/>	NON WARRANTY <input type="checkbox"/>

PAGE 1	OF 2
RE: ECN NO:	

SERIAL EFFECTIVITY MIC 704, S/N 758, 759, 771, 801 and upwards	EQUIPMENT AFFECTED RC700 RC702/MIC 704 Micro Processor
--	---

NOTE

REASON FOR CHANGE

The output signals \bar{WR} BUF, \bar{RD} BUF, \bar{IORQ} BUF, $\bar{M1}$ BUF and \bar{MRQ} BUF is floating when a DMA transport is going on. This may cause problems using the testprogram. As an example it is impossible to stop the DMA-test if this FCO is not carried out.

DESCRIPTION OF CHANGE

1. Insert the 5 resistors as shown on next page.
2. Fill in the FCO label 19-014.

ADDITIONAL COMMENTS

THE FCO-KIT CAN BE ORDERED AT THE SPARE PART STOCK UNDER RC-PARTNUMBER:
ADDRESS: HOVEDVEJEN 9, DK-2600 GLOSTRUP DENMARK

KITS FREE OF CHARGE	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
---------------------	---	-----------------------------

THE FCO-KIT INCLUDES:

QTY	DESCRIPTION	RC P/N
5	1 K OHM resistor 1/8 watt	1103057

DOCUMENTATION ENCLOSED

None

ESTIMATED INSTALLATION TIME: 0,5 h



PROJECT ENGINEER	DEVELOPMENT MANAGER	SYS. PRODUCTION MANAGER	TECH. SERVICE MANAGER
SIGN.	SIGN.	SIGN.	SIGN.
<i>M. Pedersen</i>	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>
DATE 11/2	DATE 11/2-83	DATE 12-93	DATE 12-83



FIELD CHANGE ORDER

NO. 19-014

PAGE 2 OF 2



Pin No's of Pos 110

Max height over board is 12 mm, which allows the use of Winchester adaptor.