

RCSL: 44 - RT 1911

MANDATORY	<input type="checkbox"/>	RETROFIT ON FAILURE	<input checked="" type="checkbox"/>
WARRANTY	<input type="checkbox"/>	NON WARRANTY	<input checked="" type="checkbox"/>

PAGE	1	OF	2
RE: ECN NO:	19-001		

SERIAL EFFECTIVITY	EQUIPMENT AFFECTED
N/A	RC 700 RC 721, RC 722 / KBU 721, KBU 722, KBU 72 Keyboard.

NOTE

REASON FOR CHANGE

The keyboards may be sensitive to static electricity. To prevent this the 0 Volt on the keyboard is connected to the chassis of the keyboard.

DESCRIPTION OF CHANGE

Connect the cable CBL 957 between J1 and chassis as shown on page 2.
Code the FCO-label: 19-001.

ADDITIONAL COMMENTS

THE FCO-KIT CAN BE ORDERED AT THE SPARE PART STOCK UNDER RC-PARTNUMBER: _____
ADDRESS: HOVEDVEJEN 9, DK-2600 GLOSTRUP DENMARK

KITS FREE OF CHARGE YES NO

THE FCO-KIT INCLUDES:

QTY	DESCRIPTION	RC P/N
1	CBL 957	

DOCUMENTATION ENCLOSED

None

ESTIMATED INSTALLATION TIME: 0.5 hour.

PROJECT ENGINEER	DEVELOPMENT MANAGER	SYS. PRODUCTION MANAGER	TECH. SERVICE MANAGER
SIGN. <i>[Signature]</i>	SIGN. <i>[Signature]</i>	SIGN. <i>[Signature]</i>	SIGN. <i>[Signature]</i>
DATE	DATE	DATE	DATE



FIELD CHANGE ORDER

NO.	19-001
PAGE	2 OF 2

KEYTRONIC KEYBOARD BOTTOM VIEW

