

RCSL: 44 - RT 1911

MANDATORY <input type="checkbox"/>	RETROFIT ON FAILURE <input checked="" type="checkbox"/>
WARRANTY <input checked="" type="checkbox"/>	NON WARRANTY <input type="checkbox"/>

PAGE 1 OF 2
RE: ECN NO:

SERIAL EFFECTIVITY POW 739 manufactured after 81.12.01.	EQUIPMENT AFFECTED RC700 RC702, POW 739 Power supply
--	---

NOTE

REASON FOR CHANGE

Magnetic fields generated by the switch regulator POW 739 used in RC702 may cause, that the 5 1/4" floppy disc drive in POS 2 do not work as well as a drive in POS 1.

DESCRIPTION OF CHANGE

Press the wire, from the two switch diodes, to follow the heat sink as shown on next page.

ADDITIONAL COMMENTS

THE FCO-KIT CAN BE ORDERED AT THE SPARE PART STOCK
UNDER RC-PARTNUMBER: None
ADDRESS: HOVEDVEJEN 9, DK-2600 GLOSTRUP DENMARK

KITS FREE OF CHARGE YES NO

THE FCO-KIT INCLUDES:

QTY	DESCRIPTION	RC P/N

DOCUMENTATION ENCLOSED

None

ESTIMATED INSTALLATION TIME: 0,5 h

PROJECT ENGINEER SIGN. <i>M.V. Pedersen</i>	DATE <i>22/11</i>	DEVELOPMENT MANAGER SIGN. <i>[Signature]</i>	DATE <i>23/11</i>	SYS. PRODUCTION MANAGER SIGN. <i>[Signature]</i>	DATE <i>24/11-81</i>	TECH. SERVICE MANAGER SIGN. <i>[Signature]</i>	DATE <i>23/11-81</i>
--	-------------------	---	-------------------	---	----------------------	---	----------------------

