

Vedr.: tilslutning af MF105, optisk mus.

For korrekt funktion af denne optiske mus, skal man sikre sig, at det tastatur hvortil musen tilsluttes, er opdateret korrekt.

I bunden af tastaturet er der påklæbet en mærkat. På denne mærkat skal der være trykt et nummer, der er større end, eller lig med, FCO nr. 19-090. Er den f.eks. trykt, FCO nr. 19-036, kan det ikke garanteres at musen vil fungere korrekt. Man bør således henvende sig til sin leverandør (forhandler eller RC), der er istand til at opdatere tastaturet.

Med venlig hilsen

Regnecentralen a/s

Conc.: Connection of MF105, Optical Mouse.

To obtain correct function of this optical mouse it should be secured that the keyboard to which the mouse is connected has been updated correctly.

On the rear side of the keyboard you will find a label which must be marked with a number greater than or equal to FCO No. 19-090. If for instance the label is marked FCO No. 19-036, RC cannot guarantee that the mouse will work correctly. You should, therefore, contact your supplier (vendor or RC) who will be able to update the keyboard.

Yours faithfully

RC Computer a/s