
RCSL No: 99 1 10142
Edition: May 10th, 1985
Author: John P. Pöhler

Title: RECOMMENDED SPARE PARTS AND MODULES LIST
FOR
RC759 PICCOLINE

Keywords: RC759, RC739, RC749

Abstract: This manual contains modules list and spare parts lists.

(28 printed pages)

TABLE OF CONTENTS	PAGE
1. INTRODUCTION	1
2. LIMITATIONS	1
3. UPDATING	1
4. DEFINITIONS	1
5. REPAIR LEVEL	1
6. MAINTENANCE LEVEL	2

1991 11 11 001
(copy 3/11/91)

1991 11 11 001
(copy 3/11/91)

... ..
... ..

... ..
... ..

... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..
... ..

1. INTRODUCTION

The recommended Spare Parts and Modules List consists of spare modules lists and parts lists.

2. LIMITATIONS

The modules produced for RC Computer in this product are not described on component level and have to ordered as a module.

3. UPDATING

Whether the prices are added to the spare parts list or not, the prices will be updated annually and published in the INTERNATIONAL TECHNICAL SUPPORT (ITS) GUIDE, but the prices are subject to change without notice.

It is our sincere hope that the technical staff in the field and in the workshop will find the RECOMMENDED SPARE PARTS AND MODULES LIST for the RC759 PICCOLINE a helpful and useful tool in their daily work.

4. DEFINITIONS

In the Recommended Spare Parts and Modules List the expressions REPAIR LEVEL and MAINTENANCE LEVEL are used. The definitions for each one of the two expressions are given below:

5. REPAIR LEVEL

Each of the items described in the RSML's is assigned to a certain repair level which could be one of the following:

- A. The item in question should be repaired by module replacement.
- B. The item in question should be repaired by replacement of components.
- C. The item in question may be repaired by replacement of components; but the item will not be recognized as repairable in RC COMPUTER's Central Workshop.
- D. The item in question is not repairable.

6. MAINTENANCE LEVEL

6.

Each of the items described in the RSML's is assigned to a certain maintenance level which could be one of the following:

- I. The item in question should be replaced at the customer's site.
- II. The item in question should be replaced in the local workshop.
- III. The item in question should be replaced in the central workshop.

RC 759

MODULE LIST

RC 759-1/2

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE	REMARKS
				<10 <100 <200 <300 <				
	84080006	RC 759	1					
	2801024	mainswitch pushb.	1		D	II		
	3001101	rubber foot	4	2	D	II		
	3001124	foot	4	2	D	III		
	4001009	1.5V battery AA(R6)	2	2	D	III		
	62070769	cb1 769	1	2	D	III		
	62070770	cb1 770	1	2	D	III		
	62070773	cb1 773	1	2	D	III		
	62070795	cb1 795	1	2	D	II		
	64042701	lsu 701	1	2	A	II		
	64603100	pow 749	1	2	A	II		
	83971701	dpa 701	1	2	A	III		
	84606183	cpu 740a	1	2	A	II		

RC 759/2

RECOMMENDED MODULE AND SPAREPART LIST

CPU 740

84605183 CPU 740a
101005 SN 7405 n
101083 SN 7416 n
101092 SN 75452 p
101179 SN 75489an
103006 SN 72.741 p
104012 tms 4164-15n1
104013 tms 4416-15n1
105035 1m 386
105070 cd 4049cn
105090 mm 58167an
109034 256x4 CMOS 450nS
116019 8255a-5
116053 82559a
116075 82730 b step
116085 c80186-6 b3 6mhz
121012 n82509
125001 SN 74500 n
125003 SN 74504 n
125005 SN 74510 n
125013 SN 74574 n
125014 SN 745112 n
125022 SN 745158 n
125031 SN 745373 n
125033 SN 74508 n

RD 1759

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
43701	101005	SN 7405 n	1	<100 <200 <300 <	D	III			
18808	101083	SN 7416 n	1	<100 <200 <300 <	D	III			
55909	101092	SN 75452 p	1	<100 <200 <300 <	D	III			
72800	101179	SN 75489an	1	<100 <200 <300 <	D	III			
67801	103006	SN 72.741 p	1	<100 <200 <300 <	D	III			
70516	104012	tms 4164-15n1	32	<100 <200 <300 <	D	III			
72610	104013	tms 4416-15n1	4	<100 <200 <300 <	D	III			
58218	105035	1m 386	1	<100 <200 <300 <	D	III			
55910	105070	cd 4049cn	1	<100 <200 <300 <	D	III			
43713	105090	mm 58167an	1	<100 <200 <300 <	D	III			
56500	109034	256x4 CMOS 450nS	1	<100 <200 <300 <	D	III			
43715	116019	8255a-5	1	<100 <200 <300 <	D	III			
56503	116053	82559a	1	<100 <200 <300 <	D	III			
58202	116075	82730 b step	1	<100 <200 <300 <	D	III			
58212	116085	c80186-6 b3 6mhz	1	<100 <200 <300 <	D	III			
50018	121012	n82509	1	<100 <200 <300 <	D	III			
	125001	SN 74500 n	3	<100 <200 <300 <	D	III			
	125003	SN 74504 n	2	<100 <200 <300 <	D	III			
	125005	SN 74510 n	1	<100 <200 <300 <	D	III			
	125013	SN 74574 n	2	<100 <200 <300 <	D	III			
	125014	SN 745112 n	2	<100 <200 <300 <	D	III			
	125022	SN 745158 n	2	<100 <200 <300 <	D	III			
	125031	SN 745373 n	2	<100 <200 <300 <	D	III			
	125033	SN 74508 n	2	<100 <200 <300 <	D	III			

RC 759

88310

RECOMMENDED MODULE AND SPAREART LIST

PAGE 2 OF 7
DATE 85.05.01

CPU 740

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX NO	REMARKS
				AREA			PCs		
				<100 <200 <300 <					
INT. CIRC. CONT.									
58203	125043	sn 74s163 n	1		D	III			
58213	125051	sn 74s374 n	3		D	III			
60105	125057	sn 74s32 n	2		D	III			
60106	125058	sn 74s240 n	1		D	III			
63602	125063	sn 74s299n	2		D	III			
55911	125070	sn 74s257 n	2		D	III			
62611	128001	sn 741500 n	1		D	III			
52605	128003	sn 741502 n	2		D	III			
49807	128005	sn 741504 n	1		D	III			
61801	128006	sn 741505 n	1		D	III			
62606	128007	sn 741508 n	1		D	III			
61804	128010	sn 741511 n	1		D	III			
649211	128015	sn 741527n	1		D	III			
50010	128017	sn 741530 n	1		D	III			
61805	128018	sn 741532 n	2		D	III			
	128021	sn 741538 n	1		D	III			
61815	128033	sn 7415138 n	2		D	III			
58111	128034	sn 741514 n	1		D	III			
58112	128035	sn 7415132 n	1		D	III			
58113	128038	sn 7415153 n	1		D	III			
63616	128049	sn 7415193 n	1		D	III			
63619	128051	sn 7415279 n	1		D	III			
63618	128054	sn 7415273n	2		D	III			
61904	128064	sn 7415240 n	1		D	III			

RECOMMENDED MODULE AND SPAREART LIST

CPU 740

1. CPU 740
 2. CPU 740
 3. CPU 740
 4. CPU 740
 5. CPU 740
 6. CPU 740
 7. CPU 740
 8. CPU 740
 9. CPU 740
 10. CPU 740
 11. CPU 740
 12. CPU 740
 13. CPU 740
 14. CPU 740
 15. CPU 740
 16. CPU 740
 17. CPU 740
 18. CPU 740
 19. CPU 740
 20. CPU 740
 21. CPU 740
 22. CPU 740
 23. CPU 740
 24. CPU 740
 25. CPU 740
 26. CPU 740
 27. CPU 740
 28. CPU 740
 29. CPU 740
 30. CPU 740
 31. CPU 740
 32. CPU 740
 33. CPU 740
 34. CPU 740
 35. CPU 740
 36. CPU 740
 37. CPU 740
 38. CPU 740
 39. CPU 740
 40. CPU 740
 41. CPU 740
 42. CPU 740
 43. CPU 740
 44. CPU 740
 45. CPU 740
 46. CPU 740
 47. CPU 740
 48. CPU 740
 49. CPU 740
 50. CPU 740
 51. CPU 740
 52. CPU 740
 53. CPU 740
 54. CPU 740
 55. CPU 740
 56. CPU 740
 57. CPU 740
 58. CPU 740
 59. CPU 740
 60. CPU 740
 61. CPU 740
 62. CPU 740
 63. CPU 740
 64. CPU 740
 65. CPU 740
 66. CPU 740
 67. CPU 740
 68. CPU 740
 69. CPU 740
 70. CPU 740
 71. CPU 740
 72. CPU 740
 73. CPU 740
 74. CPU 740
 75. CPU 740
 76. CPU 740
 77. CPU 740
 78. CPU 740
 79. CPU 740
 80. CPU 740
 81. CPU 740
 82. CPU 740
 83. CPU 740
 84. CPU 740
 85. CPU 740
 86. CPU 740
 87. CPU 740
 88. CPU 740
 89. CPU 740
 90. CPU 740
 91. CPU 740
 92. CPU 740
 93. CPU 740
 94. CPU 740
 95. CPU 740
 96. CPU 740
 97. CPU 740
 98. CPU 740
 99. CPU 740
 100. CPU 740

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX NO	REMARKS
				<10 <100 <200 <300 <			PCS		
		INT. CIRC. CONT.							
61816	128065	sn 7415139n	1		D	III			
61910	128068	sn 7415374 n	4		D	III			
61909	128069	sn 7415373 n	6		D	III			
64507	128078	sn 7415244n	5		D	III			
63803	128082	sn 7415390n	1		D	III			
64415	128087	sn 7415245 n	4		D	III			
66515	128088	sn 7415393 n	1		D	III			
	128117	sn 7415299n	1		D	III			
67818	136022	am 261531c	1		D	III			
		TRANSISTORS							
34114	203015	2n2907a	1		D	III			
34116	204015	2n2222a	2		D	III			
	204072	BD136	1		D	III			
		DIODES							
64510	301009	aa143	2		D	III			
11607	302020	1n 914	3		D	III			
	302050	1n 414B	2		D	III			
		ZENERDIODES							
57213	401006	bzy 88-c4v7	1		D	III			
11710	401008	bzy 88-c5v6	1		D	III			
11413	401009	bzy 88-c6v2	1		D	III			

RC 759

11003
84210

RECOMMENDED MODULE AND SPAREPART LIST

CPU 740

PAGE 4 OF 7
DATE 85.05.01

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
		CAPASITORS							
85232	814005	22n 10oct 250V	1		D	III			
84318	836009	6-25pf	1		D	III			
85002	848002	47n 12V	52		D	III			
84314	855002	220nF 50V 20% X7R	5		D	III			
86519	855003	2n2 63V 20% X7R	9		D	III			
81010	863001	22p	3		D	III			
89411	863004	100p	2		D	III			
89414	863008	1n	4		D	III			
89418	863050	10nF	1		D	III			
	863061	47nF	2		D	III			
87001	1001031	22uf 15V	10		D	III			
43918	1001032	0u1 35V	10		D	III			
86218	1001035	105UF 20V(10MR)	10		D	III			
88010	1001055	10uF/20V	2		D	III			
		RESISTORS							
	1101001	10e 5% 1/20W	3		D	III			
57307	1101025	100e 5% 1/20W	1		D	III			
	1101029	150e 5% 1/20W	1		D	III			
87310	1101031	180e 5% 1/20W	1		D	III			
57314	1101037	330e 5% 1/20W	4		D	III			
57317	1101041	470e 5% 1/20W	1		D	III			
	1101045	750e 5% 1/20W	1		D	III			
57402	1101049	1k 5% 1/20W	5		D	III			
57403	1101051	1k2 5% 1/20W	1		D	III			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 5 OF 7
DATE 05.05.01

CPU 740

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX NO	REMARKS
				<100 <200 <300 <			PCs		
		RES. CONT							
57404	1101053	1K5 5% 1/20W	1		D	III			
57406	1101057	2K2 5% 1/20W	1		D	III			
	1101059	2K7 5% 1/20W	1		D	III			
57408	1101063	3K9 5% 1/20W	1		D	III			
57409	1101065	4K7 5% 1/20W	5		D	III			
57415	1101073	10K 5% 1/20W	4		D	III			
57416	1101077	15K 5% 1/20W	2		D	III			
	1101079	18K 5% 1/20W	5		D	III			
57501	1101085	33K 5% 1/20W	1		D	III			
	1101097	100K 5% 1/20W	1		D	III			
	1101104	200K 5% 1/20W	1		D	III			
15101	1103030	75e 5% 1/8W	1		D	III			
15112	1103041	220e 5% 1/8W	1		D	III			
	1103054	750e 5% 1/8W	1		D	III			
10604	1103061	1K5 5% 1/8W	3		D	III			
	1105101	68K 5% 1/3W	1		D	III			
	1105129	1M 5% 1/3W	1		D	III			
	1105146	5M1 5% 1/3W	1		D	III			
	1106044	300e 5% 1/2W	1		D	III			
	1143013	7x33e	2		D	III			
	1143014	15x1K	2		D	III			
	1143015	15x180e	1		D	III			
	1143016	15x4K7	1		D	III			
	1144015	9x330e	1		D	III			
66512	1151001	22e 5% 1W	2		D	III			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 6 OF 7
DATE 05.05.01

CPU 740

10600

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCs	MODULE INDEX NO	REMARKS
21201		CONNEC. & SOCKETS							
21010	1307085	hdo2025p female	2		D	III			
21012	1307126	Mini-jump	7		D	III			
21013	1312013	2p	1		D	III			
21014	1312014	6p	1		D	III			
21015	1312015	5p	2		D	III			
21015	1315015	d20418-2 female	4		D	III			
21088	1315088	2x25	1		D	III			
21110	1315110	2x18p	2		D	III			
218025	1318025	9p	1		D	III			
219012	1319012	28-din	4		D	III			
219016	1319016	20-din	4		D	III			
219042	1319042	55159-1	1		D	III			
2130070	1330070	0-826629-2A	4		D	III			
2130073	1330073	0-826629-3	4		D	III			
2130081	1330081	2x20	2		D	III			
2130083	1330083	2x4D	1		D	III			
2138004	1338004	2x18p	1		D	III			
21605037	13605037	SWITCHES	1		D	III			
21605037	13605037	did	1		D	III			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 7 OF 7
DATE 85.05.01

CPU 740

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE Pcs	MODULE INDEX NO	REMARKS
		CRYSTALS							
	2701032	20MHZ	1		D	III			
72710	2701044	12.000MHZ 15dbF	2		D	III			
	2702004	32.768 KHZ 12.5 dbF	1		D	III			
		PCBAS							
	62214124	pcb 124	1		D	III			
		FIRMWARE							
	84202914	rca 914	1		D	III			
	84202955	rca 955	1		D	III			
	84202956	rca 956	1		D	III			
	84204022	pat 022	1		D	III			
	84204024	pat 024	1		D	III			
	84204063	pat 063	1		D	III			
	84204578	pat 578	1		D	III			
	84204579	pat 579	1		D	III			
	84204587	pat 587	1		D	III			
	84204594	pat 594	1		D	III			
	84204595	pat 595	1		D	III			

RC 759

MODULE LIST

PAGE 1 OF 1
DATE 85.05.01

RC 739-001

ORDER NO	VENDOR	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCs	MODULE INDEX NO	REMARKS
			<10	<100 <200	<300	<			

84080019 RC 739-001

62090574 kb1 574
 62301209 ksa 739
 84076752 kbc 752

1 2 4
 1 2 3
 1 2 3

A A A

I II II

DANISH

NO MO
 ORDER NO DESCRIPTION
 UNIT PRICE

850501
 850502
 850503
 850504
 850505
 850506
 850507
 850508
 850509
 850510

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

KBC 752

ORDER NO	VENDOR	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
NO	NO		<10	<100	<200	<300			
84075752	KBC 752		1	2	3	3	A	II	
	INT. CIRC.								
105070	6C4049C	6C4049C	1				D	III	
105076	6C4514BCN	6C4514BCN	1				D	III	
1116077	8039 6MHZ	8039 6MHZ	1				D	III	
120025	7805UCF	7805UCF	1				D	III	
128006	5N 741505 n	5N 741505 n	3				D	III	
128069	5W 7415373 n	5W 7415373 n	1				D	III	
TRANSISTORS									
203015	2n2907a	2n2907a	1				D	III	
204015	2n2222a	2n2222a	1				D	III	
DIODES									
302050	1n 414B	1n 414B	7				D	III	
LEDs									
701012	220	220	1				D	III	
CAPACITORS									
648002	47n 12V	47n 12V	6				D	III	
660015	220+/-10/630V	220+/-10/630V	1				D	III	
660018	330+/-10/630V	330+/-10/630V	1				D	III	
871040	1n5/2.5/160V	1n5/2.5/160V	2				D	III	
1001044	0u47/35V	0u47/35V	1				D	III	
1001054	22uf/20V	22uf/20V	2				D	III	

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 2 OF 2
DATE 85.05.01

KBC 752

ORDER NO	VENDOR	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
NO	NO		<10 <100 <200 <300 <						
RESISTORS									
15110	1103039	180e 5% 1/8W	2		D	III			
15114	1103043	270e 5% 1/8W	1		D	III			
10600	1103057	1k 5% 1/8W	7		D	III			
	1103071	3k9 5% 1/8W	1		D	III			
10704	1103081	10k 5% 1/8W	4		D	III			
68219	1144004	5X10K	1		D	III			
CONNEX. & SOCKETS									
	1314021	phonecon. 600s 4com	1		D	III			
	1315079	10b	1		D	III			
60005	1319011	24-pin socket	1		D	III			
SWITCHES									
08028	1517002	53137-1	1		D	III			
RELAYS									
	1605035	monostabil 6vdc	1		D	III			
CRYSTALS									
	2701028	5.9904 MHz	1		D	III			
PCBAS									
	62214669	pcb 669	1		D	III			
FIRMWARE									
	84205405	roc 405	1		D	III			

RC 759

MODULE LIST

PAGE 1 OF 1
DATE 85.05.01

RC 749

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
99318	90101175	RC 749	1	3	A	I			
10960	10304005	colour monitor	1	2	A	I			
12114	62070787	cbi 787	1	2	A	I			
12110	65240025	cbi 440/250	1	2	A	I			

MD MILL (10) (100) (500) (2000) EACH

MD IN MD OR MILL IN BEWARE

REPAIR LEVEL

MAINT. LEVEL

PRICE

MODULE INDEX

1500 125000

RC 749

RC 749

RC 749

RC 739
 85000000
 85000000
 85000000
 85000000

RECOMMENDED MODULE AND SPAREPART LIST
 LSU 701

ORDER NO. 64042701
 VENDOR
 DESCRIPTION
 100 302

NO. 64042701
 ORDER NO. 100 302
 VENDOR
 DESCRIPTION
 100 302

ORDER NO.	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX	REMARKS
			AREA			PCS	NO	
72802	LSU 701	1	2	A	II			
	CONNEX. & SOCKETS	1	2					
	1x2pol minilatch	1	2					
	47439 socket	4	2		III			
	1x3pol minilatch	1	2	D	III			
	LAUDSPEAKERS	1	2					
	laudsp. AD2071/Z8	1	2	D	III			

NO. 64042701
 ORDER NO. 100 302

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 1 OF 5
DATE 85.05.01

POW 749

ORDER NO	VENDOR	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE Pcs	MODULE INDEX NO	REMARKS
64603100	POW 749	POW 749	1	2	A	II			
2401046	TRF 703	TRF 703	1	2	A	II			
61903045	TRF 703	TRF 703	1	2	A	II			
64603102	TRF 703	TRF 703	1	2	A	II			
64603103	TRF 703	TRF 703	1	2	A	II			

MODULES

TRF 703
 TRF 703
 TRF 703
 TRF 703
 TRF 703

TRF 703

TRANSFORMERS
trafo

CABLES

cb1 791
 cb1 792
 cb1 793
 cb1 794

NO OF UNITS IN SERVICE AREA
 (10) (100) (200) (300) (400) (500) (600) (700) (800) (900) (1000)

REPAIR LEVEL
 A B C D E F G H I J K L M N O P Q R S T U V W X Y Z

MAINT. LEVEL
 I II III

PRICE Pcs

MODULE INDEX NO

REMARKS

END

RC 759

RECOMMENDED MODULE AND SPAREART LIST

POW 749

POWER BUSES

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
64603102	NEF 701	RESISTORS							
	1103129	1M 5% 1/BW	1		D	III			
	1510029	main	1		D	III			
	1901167	2x10mH/0.5A	1		D	III			
	1901168	4(6)uH, 1.5A	2		D	III			
	2003002	NOISE FILTERS							
	2003003	0uH/250V 110A	1		D	III			
	2101027	FUSES							
	2102024	holder	1		D	III			
	2118002	0a5 sb 5x20	1		D	III			
	62214131	PCBAs							
		pcb 131	1		D	III			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

POW 749

ORDER NO	VENDOR	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
300008	300008	DIODES	1		D	III			
300009	300009	DIODES	1		D	III			
300010	300010	DIODES	1		D	III			
300011	300011	DIODES	1		D	III			
300012	300012	DIODES	1		D	III			
300013	300013	DIODES	1		D	III			
64603103	64603103	RGM 701	1		D	III			
105026	105026	INT. CIRC.	1		D	III			
105045	105045	INT. CIRC.	1		D	III			
105049	105049	INT. CIRC.	1		D	III			
203039	203039	TRANSISTORS	2		D	III			
204015	204015	TRANSISTORS	1		D	III			
302045	302045	DIODES	1		D	III			
302058	302058	DIODES	1		D	III			
302072	302072	DIODES	1		D	III			
303017	303017	ZENER DIODES	1		D	III			

300014
300015
300016
300017
300018
300019
300020
300021
300022
300023
300024
300025
300026
300027
300028
300029
300030
300031
300032
300033
300034
300035
300036
300037
300038
300039
300040
300041
300042
300043
300044
300045
300046
300047
300048
300049
300050
300051
300052
300053
300054
300055
300056
300057
300058
300059
300060
300061
300062
300063
300064
300065
300066
300067
300068
300069
300070
300071
300072
300073
300074
300075
300076
300077
300078
300079
300080
300081
300082
300083
300084
300085
300086
300087
300088
300089
300090
300091
300092
300093
300094
300095
300096
300097
300098
300099
300100

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

POW 749

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX NO	REMARKS
NO	NO		<10	<100 <200 <300 <	LEVEL	LEVEL	PCs	NO	
POT. METERS									
67915	1205045	2k2	1		D	III			
CONNECTORS									
68707	1318025	6.35mm 9D	1		D	III			
COILS									
67910	1901125	drossel dk8266	1		D	III			
68707	1501144	drossel 6uH-6A	1		D	III			
FUSES									
69503	2101022	holder 1611 dr	1	410					
20718	2102011	1ag slow 5x20	1	100					
20719	2102017	6a3 slow 5x20	1	100					
PCBAS									
62214127		pcb 127	1		D	III			
64603110		pcb 701	1		A	II			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

PAGE 4 OF 5
DATE 85.05.01

POW 749

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE	MODULE INDEX	REMARKS
NO	NO		<100	<100 <200 <300 <	LEVEL	LEVEL	PCs	NO	
CAPACITORS									
66518	855001	100nF 50V 20%	8		D	III			
66519	855002	220nF 50V 20%	1		D	III			
68511	863050	100nF 50V 20%	1		D	III			
69515	871037	680p/2.5/160V	1		D	III			
	909009	4700uF/40V	1		D	III			
	909010	1000uF/40V	2		D	III			
	909012	470uF/40V	1		D	III			
	909013	2200uF/40V	1		D	III			
	932001	22uF/35V	1		D	III			
57001	1001031	22uF 15V	1		D	III			
RESISTORS									
014516	1103013	15e 5% 1/8W	1		D	III			
	1103022	36e 5% 1/8W	1		D	III			
15108	1103037	150e 5% 1/8W	1		D	III			
15116	1103045	330e 5% 1/8W	1		D	III			
10600	1103057	1k 5% 1/8W	1		D	III			
10604	1103061	1k5 5% 1/8W	1		D	III			
10612	1103069	3k3 5% 1/8W	1		D	III			
	1103076	6k2 5% 1/8W	1		D	III			
	1103121	470k 5% 1/8W	1		D	III			
67909	1147002	r047 3W	1		D	III			

RC 759

RECOMMENDED MODULE AND SPAREPART LIST

ORDER NO	VENDOR NO	DESCRIPTION	NO IN EACH UNIT	NO OF UNITS IN SERVICE AREA	REPAIR LEVEL	MAINT. LEVEL	PRICE PCS	MODULE INDEX NO	REMARKS
72805	83971701	DPA 701	1	2	A	II			
67818	136022	INT. CIRC. am 261531c	5		D	III			
67817	136023	am 261532	3		D	III			
43911	848002	CAPACITORS 47n 12V	4		D	III			
57001	1001031	22uf 15V	2		D	III			
57310	1101031	RESISTERS 180e 5% 1/20w	2		D	III			
	1143011	8x150e	1		D	III			
	1143012	8x11k	1		D	III			
	1144058	3x10e	1		D	III			
18418	1307086	CONNECTERS h020370 female	1		D	III			
	1315015	d20418-2 female	2		D	III			
	1325098	2x6.8	1		D	III			
	62214125	PCBAs pcb 125	1		D	III			
	84204577	FIRMWARE pat 577	1		D	III			

RETURN LETTER

Title: Recommended spare parts and modules RCSL No.: 99 1 10142
list for RC759 Piccoline
A/S Regnecentralen af 1979/RC Computer A/S maintains a continual effort to improve the quality and usefulness of its publications. To do this effectively we need user feedback, your critical evaluation of this manual.

Please comment on this manual's completeness, accuracy, organization, usability, and readability:

Do you find errors in this manual? If so, specify by page.

How can this manual be improved?

Other comments?

Name: _____ **Title:** _____
Company: _____
Address: _____

Date: _____

Thank you

..... **Fold here**

..... **Do not tear - Fold here and staple**

**Affix
postage
here**

REGNECENTRALEN
at 1979

**Information Department
Lautrupbjerg 1
DK-2750 Ballerup
Denmark**